

Attorney Docket No. 837.1979

## IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent Application of:

Fumitake SUZUKI, et al.

Certificate

MAY 2 0 2004

Application No.: 10/046,223

**ATTENTION** 

CERTIFICATE OF CORRECTION

of Correction

Confirmation No.: 4399

Filed: January 16, 2002

U.S. Patent No.: 6,715,934 B2

**BRANCH** 

Batch No.:

Issued: April 6, 2004

For:

RECEPTACLE TYPE OPTICAL MODULE AND PRODUCTION METHOD THEREFOR

## REQUEST FOR CERTIFICATE OF CORRECTION

Commissioner for Patents PO Box 1450 Alexandria, VA 22313-1450

Sir:

Patentees respectfully request that a Certificate of Correction be issued in the subject patent, pursuant to 35 USC § 254 and 37 CFR § 1.322, to correct the error shown on the attached Form PTO-1050. A check in the amount of \$100 to cover the cost of the Certificate is attached.

One or more of the errors shown on the attached Form PTO-1050 is or are within the responsibility of the undersigned; each thereof is of a clerical or typographical nature or of minor character and occurred in good faith, and the correction thereof is consistent with the prosecution record.

Respectfully submitted,

05/17/2004 WABRHAM2 00000220 6715934

01 FC:1811

100.00 OP

STAAS & HALSEY LLP

Date: 1/1/19/14/100

Geñe M. Garner II

Registration No. 34,172

1201 New York Ave, N.W., Suite 700

Washington, D.C. 20005 Telephone: (202) 434-1500

Facsimile: (202) 434-1501

MAY 2 0 2004

Best Available Copy

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. (Also Form PTO-1050)

## UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO : 6,715,934 62

**DATED**: April 6, 2004

INVENTOR(S): Fumitake SUZUKI, et al.

Column 8, line 29, delete "rein" and insert --resin--.

MAILING ADDRESS OF SENDER: STAAS & HALSEY LLP 1201 New York Ave., N.W. Suite 700 Washington, DC 20005 PATENT NO. 6,715,934 B 2

No. of add'l copies @ 50¢ per page

MAY 2 0 2004